K3000™

Medium Duty - General repair and maintenance jobs such as mining, construction, and all types of metal fabrication



AMPERAGE RANGE

■ 90 - 600 amps

ELECTRODE SIZE

- Pointed 1/8" 3/8" round (3.2 mm 9.5 mm)
- Jointed 5/16" 3/8" round (7.9 mm 9.5 mm)
- Flat 3/8" and 5/8" (9.5 mm 15.9 mm)
- Half Round 5/8" (15.9 mm)

AIR REQUIREMENTS

- psi 80
- kg/cm² 5.6
- cfm 22
- I/min 624

Part No.	Description		
01-065-001	Torch Only		
61-065-006	Torch w/7 ft (2.1 m) 360° Swivel Cable		
61-065-002	Torch w/7 ft (2.1 m) 360° Swivel Cable & Insulated Hook-Up Kit		
61-065-007	Torch w/10 ft (3 m) 360° Swivel Cable		
61-065-003	Torch w/10 ft (3 m) 360° Swivel Cable & Insulated Hook-Up Kit		

K4000®

Heavy Duty - Heavy metal removal applications such as weld preparations in pressure vessel shops and shipyards



AMPERAGE RANGE

■ 90 - 1000 amps

ELECTRODE SIZE


- Pointed 5/32" 1/2" round (4.0 mm 12.7 mm)
- Jointed 5/16" 1/2" round (7.9 mm 12.7 mm)
- Flat 3/8" and 5/8" (9.5 mm 15.9 mm)
- Half Round 5/8" (15.9 mm)

AIR REQUIREMENTS

- psi 80
- kg/cm² 5.6
- cfm 25
- I/min 708

Part No.	Description		
01-082-002	Torch Only		
61-082-008	Torch w/7 ft (2.1 m) 360° Swivel Cable		
61-082-006	Torch w/7 ft (2.1 m) 360° Swivel Cable & Insulated Hook-Up Kit		
61-082-009	Torch w/10 ft (3 m) 360° Swivel Cable		
61-082-007	Torch w/10 ft (3 m) 360° Swivel Cable & Insulated Hook-Up Kit		

SWIVEL CABLE ASSEMBLY OPTIONS



Part No.		Description
K3000	K4000	Description
70-088-107	70-084-207	7 ft (2.1 m) 360° Swivel Cable Assembly
70-088-110	70-084-210	10 ft (3 m) 360° Swivel Cable Assembly



